


US EPA ARCHIVE DOCUMENT

1. Incident Name	2. Date Prepared	3. Time Prepared	UNIT LOG ICS 214	
Kalamazoo River/Enbridge Spill	05/15/2012	1800		
4. Unit Name/Designators	5. Unit Leader		6. Operational Period :	
SOTF Team #1	Name:	Dan Capone & Joe Victory (START/US EPA)	From:	05/15/2012 0800
	Position:	Operations Section Chief	To:	05/15/2012 1800
7. Personnel Roster Assigned				
Name	ICS Position	DUTY CELL		
Dan Capone	Operations Section Chief			
Joe Victory	Operations Section Chief			
Dan Zahner	Field Team Lead			
Jose Aguilera	SOTF#1			
8. Activity Log				
Activity Area	MP2.25-4.0	LAT	LAT	
		Various	Various	
		(DD.MMMM)	(DD.MMMM)	
<u>OIL OBSERVED</u>	EXTENT OF OIL IMPACTED AREA	NA		
	DENSITY OF OIL /SHEEN	NA		
Total Collection Points	NA			
Total Boom Deployed	NA			
Activity	<u>START SOTF Team #1Activity:</u> SOTF # 1 conducted oversight of Enbridge's Team A poling re-assessment activities. Team A members Mike Neal Poling leader, Russell Patte GPS/Leica operator. Team A conducted Target Bathymetry Location data collection; 13 points were recorded in the GPS/Leica instrument including water level at those locations. Data is downloaded into the hydrodynamic model. Team A conducted 31 poling locations, 4 with light sheen and 27 with no visible contamination. Temperature readings in the sediment ranged from a low of 63 to a high of 69 degrees Fahrenheit. Bed and water temperatures where a few degrees higher reaching up 71 degrees. Areas poled today consisted mostly of sand and gravel with relatively fast flow, heavy vegetation and visible small to large size fish.			
Health and Safety Issues	None			
Comments	None			